

Sub-Contractor Acceptance and Use of Fermilab Tools/Equipment

1.Describe item loaned: Model Number		Serial Number		
Genie Lift, GL-8		1300-14124 (#1)	(#2)	
Cotterman AlumaSteps (st	epladder)	#1]#4	
2. TOOL INSPECTION				
☐ Acceptable ☐ Unacceptable				
If unacceptable, describe the issue (tool cannot	be loaned until rep	paired):		
The contractor accepts that there is risk involve that the tools have been inspected and found sa				
hereby that he has had sufficient training to safe			o commence to transcer or cortained	
4. Thereforeaccepts the too	ols for the purpose	intended and will ho	old Fermilab harmless if an injury	
occurs due to the use of the listed tool/s.				
Sub-contractor Superintendent Signature	Supt. pri	inted name	Date	
5. RETURN OF TOOL/EQUIPMENT				
Was the tool/equipment returned in good wor	king order?	∐ Yes ∐ No		
			<u> </u>	
Task Manager/Construction Coordinator Print	ted Name/Signatu	re Date		
6. ACCIDENT/INCIDENT				
I certify that while using the tool identified abo	ove, I was not injur	ed in any way.		
			<u> </u>	
Subcontractor Employee-Signature	Printed name	Date		
Fermilab Representative-Signature	Printed Name	Date		
Distribution: Contract Administrator (Original) T&M Manager (T&M contract				
ES&H Form #20	o oruy)		09/2001	

Fermilab ES&H Manual 7020-1